





DWP-5000FL



WEIGHING INDICATOR


User Manual


Rev1.1

---

		<p>WARNING</p>
	<p>Ask professional personnel to debug, detect and repair indicator.</p>	

		<p>WARNING</p>
	<p>Please keep good grounding of indicator.</p>	

	<h2>WARNING</h2>
<p>In electrical connection of indicator, please cut off the power supply in advance. Wait for 30 seconds between power-on of the indicator for 2 times.</p>	

	<h2>Pay Attention to Static Electricity</h2>
<p>The indicator is a device sensitive to static electricity, thus please take anti-static precautions in use and maintenance.</p>	

# CONTENTS

<b>1. TECHNICAL PARAMETERS .....</b>	<b>1</b>
<b>2. MAIN FUNCTIONS .....</b>	<b>1</b>
<b>3. BOUNDARY DIMENSION .....</b>	<b>2</b>
<b>4. INTRODUCTION OF PANEL .....</b>	<b>2</b>
<b>5. INTRODUCTION OF KEYS .....</b>	<b>3</b>
<b>6. FUNCTIONS.....</b>	<b>3</b>
<b>7. SETTING AND CALIBRATION .....</b>	<b>7</b>
<b>8. CONTINUOUS OUTPUT FORMAT SPECIFICATION .....</b>	<b>12</b>

## Technical parameters

- Data Transfer: Wireless: From weighing scale to indicator data transfer methods is bluetooth.

- Bluetooth interface (Optional)

- Version of bluetooth: BLE5.0

Maximum transmitted power: +4dbm    Antennae: PCB antennae

- 3.5”TFT color screen display

- 6 function buttons. Operation is simple and convenient

- IP grade: IP5x

- Inner resolution: 1 million

- Weight upgrading rate: 10 times per second

- Power supply mode

DC 12V $\pm$ 10% or DC 24V $\pm$ 10%

- Micro thermal printer (Optional)

- Operating temperature: -10°C-40°C, relative humidity < 85 %

- Storage temperature: -20°C~60°C, relative humidity < 85 %

## 1. Main functions


- Basic weighing function: resetting, removing the peel, clearing the peel and accumulation.

- Automatic screen saver and automatic shutdown for energy-saving function


- Customized printing formats and communication protocol

## 2. Boundary dimension







Instrument size: detailed as below figure (mm); instrument weight: 2.0kg



### 3. Introduction of panel



## 4. Introduction of keys

Sign	Mode	Short press	Long press
	Normal	Turn on	Turn off
	Reset	Return	-
	Normal	-	Enter calibration
	Reset	Move cursor to left	-
	Normal	Add current weight to total	Clear the total
	Reset	Move cursor to right	-
	Normal	Tare (gross weight to net weight)/ Remove the tare (net weight to gross weight)	Enter to adjust the angle difference
	Reset	Choose the next setting Number decrease	-
	Normal	Zero key	Enter to check the internal code of left/right fork
	Reset	Choose the previous setting Number increase	-
	Normal	Print	Enter reset menu
	Reset	Confirm	-

## 5. Function

### 1. Manual zeroing (semi-automatic)

- A. Press [ZERO] key to make the indicator return to zero
- B. The display value deviates from the zero point, but when it is within zero setting range, the [ZERO] key works. Otherwise, the [ZERO] key will not work. For the parameter selection and setting method of the zero setting range, please refer to the relevant chapters of the parameter setting.
- C. The zeroing operation can be performed only when the stability sign is bright.

## 2. Peeling and clearing operation

In the weighing display state, when the displayed weight is positive and weighing is stable, press the [Tare] key to deduct the displayed weight value as the tare weight. At this time, the indicator shows that the net weight is 0, and the symbol is “G\B” change to “Net”, then press [Tare] key to clear the tare weight, return to the gross weight state, and the symbol changes from “Net” to “G\B”.

## 3. Accumulation and accumulative weight clearing operation

### A. Accumulation operation

In the weighing display state, when the displayed weight is positive and the weighing is stable, press the [Add] key, the accumulated times will increase by 1 and the current weight will be accumulated into the accumulation unit as shown in the figure below:

Before accumulation



After accumulation



## B. Accumulative weight clearing operation

Press and hold the [Add] key for about 2 seconds until "Total: 0" and "Count: 0" are displayed, indicating that the accumulated weight has been cleared. As shown below:



## 4. Printing operation


### A. Weighing ticket printing

In the weighing display state, when the displayed weight is positive and the weighing is stable, press the [Print] key, and the printer will print the current weighing ticket in the following format:



## B. Cumulative weight printing

In the weighing display state, quickly press the [Print] key twice, the printer will print the current accumulated times and accumulated weight in the following format:



A printed receipt with the following text:

```
TOTAL TICKS
-----
Date: 09/08/2022
Time: 14:42:15
Count: 5
Total: 8193kg
```



**Below instructions only for trained engineer.**



## 6. Setting and calibration:

Long press “Print”, enter system setting menu, press“ ▲ ”or“ ▼ ”;


Pick up the parameter ( **the chosen one is in red** ) , press“ ↵ ”enter menu of next level or confirm the setting 。 Press“ ⏪ ”to return to the menu of previous menu。

When input the number, press “ ◀ ” “ ▶ ” to move the cursor to left and right. Press “ ▲ ” “ ▼ ”to change the number。




### A、 Parameter setting of scale

 <p>Setup menu</p> <p>▶ System setup</p> <p>Application</p> <p>Uarts setup</p> <p>Management</p> <p>Maintenance</p>	<p>Long press “Print” to enter system setup menu. Press “Print” to enter the menu of next level.</p>
 <p>System setup</p> <p>▶ Capacity</p> <p>Indexing</p> <p>Unit</p> <p>Powerup zero</p> <p>Keypad zero</p> <p>Auto zero</p> <p>Filter</p>	<p>Description of system parameter:</p> <p>Capacity: 1-20000 (optional)</p> <p>Indexing: 1、 2、 5、 10、 50 (optional)</p> <p>Unit: kg、 lb、 g、 t、 N (optional)</p> <p>Power up zero: off、 5%、 10%、 20%、 50% (optional)</p> <p>Keypad zero: off、 5%、 10%、 20%、 50% (optional)</p> <p>Auto zero: off、 1、 2、 3、 4、 5 (optional)</p> <p>Filter: 0、 1、 2、 3、 4、 5 (optional)</p>

## B、Check the internal code of left and right fork

	<p>Long press “Zero” to check the internal code of left and right fork.</p> <p>Apply force to the weighing area of forks and observe the change of internal code for checking the working condition of forks and bluetooth.</p>
---	---

## C、Angle adjustment




	<p>Long press “Tare” to enter the setting of angle adjustment. It will remind to remove the weight applied to left and right forks.</p> <p>Remove the weight and press “Print” to enter the menu of next level.</p>
	<p>It will remind to apply weight to left fork. Please intention the capacity of weight should be more than 200kg.</p> <p>Observe the change of internal code. When the number is stable, press “Print” to enter the menu of next level.</p>
	<p>It will remind to apply weight to right fork. When put weight to right one, please intention to apply the same capacity with that of the left fork.</p> <p>Observe the internal code. When the number is stable, press “Print” to enter the menu of next level.</p>

<div data-bbox="371 181 659 582"> <p><b>Angle Adjust</b></p> <p>Unload all. Load left. Load right. <b>Opertion end.</b></p> <hr/> <p>L.code 53817 R.code 82453</p> </div>	<p>It will show “operation end” Press “Print” or “Return” to go back to the main menu.</p>
---	--

## D、Calibration

<div data-bbox="371 792 659 1171"> <p><b>Calibrating</b></p> <p><b>Calibrate Zero</b></p> <p>Calibrate Span</p> <hr/> <p>L.code 2 R.code 0</p> </div>	<p>Long press “Cal” to enter calibration. Please ensure finish angle adjustment before calibration. Press “Zero” or “Tare” for choosing zero point calibration or loading point calibration. If it is the first time of calibration, zero point calibration, and then loading point calibration. Press “Print” to enter the zero point calibration</p>
<div data-bbox="371 1216 659 1626"> <p><b>Calibrating</b></p> <p>Calibrate Zero</p> <p><b>Unload...</b></p> <p>Calibrate Span</p> <hr/> <p>L.code 0 R.code 0</p> </div>	<p>Zero point calibration. It will remind to remove the weight applied to scale and keep no weight on the scale. When the internal code is stable, press “Print ” to enter menu of internal code sampling.</p>

<div data-bbox="368 181 662 584"> <p><b>Calibrating</b></p> <p>Calibrate Zero Sample... Calibrate Span</p> <p>L.code -17 R.code 16</p> </div>	<p>Sampling in zero point calibration. After sampling finish, enter next level menu. Zero point calibration ends.</p>
<div data-bbox="368 638 662 1041"> <p><b>Calibrating</b></p> <p>Calibrate Zero Operation end Calibrate Span</p> <p>L.code -1 R.code 2</p> </div>	<p>When showing zero point calibration ends, then loading point calibration. Press “Print” to enter loading point calibration.</p>
<div data-bbox="368 1095 662 1543"> <p><b>Calibrating</b></p> <p>Calibrate Zero Operation end Calibrate Span Points: 2</p> <p>L.code 2 R.code 0</p> </div>	<p>Setting the number of loading points. If only calibrate the zero point and one loading point, set Points to “2” . After setting the number of calibration points, press “Print” to next menu.</p>
<div data-bbox="368 1597 662 2036"> <p><b>Calibrating</b></p> <p>Calibrate Zero Operation end Calibrate Span Points: 2 Load the 2nd</p> <p>L.code 9611 R.code 0</p> </div>	<p>It reminds to apply weight (2<sup>nd</sup> loading point) Weight can be put on either left or right fork. It is better to put weight onto both two forks (bear the weight evenly) After putting the weight, observe the change of internal code. Press “Print” to enter menu of next level when the code is stable.</p>

 <p><b>Calibrating</b></p> <p>Calibrate Zero Operation end</p> <p>Calibrate Span Points: 2 Wt: 0000 kg</p> <p>L.code 9610 R.code 0</p>	<p>Input the number of the applied weight. Switch the cursor with “Cal” &amp; “Add” ; Change the number with “Tare” &amp; “Zero”</p> <p>Input the right number and press “Print” to enter sampling interface.</p>
 <p><b>Calibrating</b></p> <p>Calibrate Zero Operation end</p> <p>Calibrate Span Points: 2 Sample....</p> <p>L.code 9611 R.code 0</p>	<p>After sampling, enter to next interface.</p>
 <p><b>Calibrating</b></p> <p>Calibrate Zero Operation end</p> <p>Calibrate Span Points: 2 Operation end</p> <p>L.code 9612 R.code 0</p>	<p>Loading point calibration ends, press “Print” or “return” to back to main menu.</p>

## 7. Continuous output format specification

Start of text	Current total weight	Left fork weight	Right fork weight	End of text
0x02	XXXXXX	YYYYYY	<i>ZZZZZ</i>	0x0d 、 0x0a
<p>1、 Weight value is ASCII text.</p> <p>2、 <math>XXXXXX = YYYYYY + ZZZZZ</math>.</p> <p>3、 Transmission frequency: 20 FPS.</p> <p>4、 Example: 0x02 0x30 0x30 0x33 0x30 0x30 0x30 0x30 0x31 0x30 0x30 0x30 0x30 0x32  0x30 0x30 0x0d 0x0a  Example: Total weight:300kg, Left fork weight: 100kg, Right fork weight: 200kg</p>				